

TECHNICAL BULLETIN

No. NTKO2-0517-6

May 2017

<u>Topic</u>

Spark Plug damage due failure to replace O2 Sensors at specified replacement interval

<u>Issue</u>

Drivability problems and/or severe engine damage is possible as a result of failing to replace the O2 Sensor at specified replacement intervals. Failing to replace sensors when recommended and/or relying on DTC codes <check engine> may lead to severe engine damage (Spark Plug ground strap, center electrode melting) as a result of a clogged catalytic converter due to carbon or other contaminates. This clogging will increase combustion chamber heat by increased back pressure destroying the Spark Plugs and eventually the catalytic converter itself.

<u>Solution</u>

Follow O2 sensor specified replacement intervals according to vehicle or O2 sensor supplier service recommendations.

Additional Information

Note: Any damage resulting from not following service replacement recommendations will not be considered for warranty coverage

